

This is the route I use to go to work and to visit the local café. Please have a look at the pictures to see the obstacles I face along the way.



There is a high step where the footpath ends. I need to hold onto the wall to help me get down the step.



As you can see from this photo the ground is very uneven to get to the next footpath. There is also a big step up on the other side.



I have to walk over towards the shops so that I can hold onto the wall. This helps me to get onto the footpath safely.



This is the route I use to go to work and to visit the local café. Please have a look at the pictures to see the obstacles I face along the way.



I also use this route to get to work and to visit the local coffee shop. I have a visual impairment so the uneven footpath and lack of safe crossings makes it really difficult for me.



Again you can see the uneven road surface and high steps to get from one footpath to another.

